LANTRONIX®

167 Technology Dr.

Irvine | CA 92618 | USA

Tel: 949-453-3990

Fax: 949-453-3995

www.lantronix.com

Date: 10/29/2012   **PCN No.:**   **191**

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

Lantronix is pleased to announce the release of new and improved MatchPort b/g Pro firmware version 5.2.0.3R2.

The easy upgrade to firmware version 5.2.0.3R2, will be available at the Lantronix website, offers several improvements including:

- Support for standard Line speed 110 bps and custom speeds down to 110 bps.
- Multiple socket connections to same port.
- Improved XML import
- Configurable maximum retransmissions for TCP
- Improved CLI features
- Improved SDK features
- DHCP to AutoIP failover
- Modbus protocol with optional RSS Trace
- New SNMP features
- TFTP enhancements
- SSL improved

Full details of all the additions to this software update are available in the release notes.

Part Numbers	Product Description	Current Revision	New Revision with Firmware 5.2.0.3R2
MPP3002000G-01	**MatchPort b/g Pro** 802.11 Wireless Device Server, bulk	B12	C12
MPP300200SG-01	**MatchPort b/g Pro** 802.11 Wireless Device Server, Sample	B14	C14

SCHEDULE: Please note that factory shipments with new MatchPort b/g version 5.2.0.3R2 will approximately begin shipping on **May 1st, 2013.**

For customers that would like to take advantage of the new capabilities immediately, the new firmware and associated release notes will be available for download from our website on **November 1st, 2012**. http://www.lantronix.com/support/downloads.html

If you have any questions, please contact your sales representative or Lantronix Customer Support at (866) 649-0721 or (949) 453-3990 x342.

Product Management

LANTRONIX®