

March 14, 2008  
 PCN No. 088

## PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

The purpose of this communication is to inform you that the Lantronix SecureLinX™ Branch Office Manager (SLB) and SecureLinX Secure Console Server (SLC) products require a rework to the main printed circuit board assembly (PCBA) to be compatible with newer compact flash cards available from our supplier.

This rework does not affect the form, fit, or firmware function of the unit, but simply allows us to more easily adapt to the newer flash cards. The change will be phased in over the next 3 to 6 months.

For quality and tracking purposes, the manufacturing revision numbers on the product label will be revised. New revision numbers are also listed in the table.

Part Number	Current Revision	New Revision
SLB088411-01	A16	A17
SLB088412-01	A12	A13
SLC00824T-02	F20	F21
SLC01624T-02	F19	F20
SLC03224T-02	F19	F20
SLC00812N-02	G22	G23
SLC00822N-02	F18	F19
SLC03212N-02	F17	F18
SLC03222N-02	F17	F18
SLC01612N-02	F17	F18
SLC01622N-02	F17	F18
SLC04812N-02	F17	F18
SLC04822N-02	F17	F18
SLC04824T-02	G21	G22
SLC04812N-01	K23	K24
SLC01612N-01	K23	K24
SLC03212N-01	K23	K24
SLC01622N-01	K23	K24
SLC03222N-01	K23	K24

Part Number	Current Revision	New Revision
SLC04822N-01	K23	K24
SLC01624T-01	K26	K27
SLC03224T-01	K26	K27
SLC04824T-01	K26	K27
SLC00812N-01	L26	L27
SLC00822N-01	L25	L26
SLC00824T-01	L29	L30
SLC00812N-G2	F17	F18
SLC00822N-G2	F17	F18
SLC00824T-G2	F18	F19
SLC01612N-G2	F17	F18
SLC01622N-G2	F17	F18
SLC01624T-G2	F19	F20
SLC03212N-G2	F17	F18
SLC03222N-G2	F17	F18
SLC03224T-G2	F18	F19
SLC04812N-G2	F17	F18
SLC04822N-G2	F17	F18
SLC04824T-G2	F18	F19

If you have any questions, please contact your sales representative or Lantronix Customer Support at (866) 649-0721 or (949) 453-3990 x342.