

Date: 11/17/2014

PCN No.: 250

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

This is to inform you that a change will be made to the following products. This notification is for your information.

Change Type

Device Firmware

Products Affected

Part Number	Product Description	Old Rev	New Rev
MP1001000G-01	MatchPort B/G Wireless Device Server, 802.11 b/g, RoHS, Bulk	E18	F18
MP1002000G-01	MatchPort B/G Wireless Device Server, 802.11 b/g, AES Encryption, RoHS, Bulk	E18	F18
MP100200SG-01	MatchPort B/G Wireless Device Server, 802.11 b/g, AES Encryption, RoHS, Sample	E18	F18
MP5002000-01	MatchPort NR Device Server, AES Encryption, RoHS, Bulk	A11	B11
MP500200S-01	MatchPort NR Device Server, AES Encryption, RoHS, Sample	A11	B11

Description and Extent of Change

Lantronix is pleased to announce the release of new application firmware version **6.10.0.1** and Web Manager version **2.0.0.6** for MatchPort B/G and MatchPort NR. The new firmware offers several improvements, including:

- Build environment changed to support new Paradigm Tools
- RFC2217 enabled so high speed baud rates (460k/921k) can pass data regardless of serial port speed
- Implement new monitor mode command to show full firmware release version
- Miscellaneous bug fixes

Refer to the release notes for a complete listing of additional features and bug fixes.

For customers that would like to take advantage of the above new capabilities, the firmware will be available for download from our website by November 25, 2014:

<http://www.lantronix.com/support/downloads.html>

Effect of Change on Fit, Form, Function, Quality, or Reliability

Change is limited to product functionality.

Effective Date of Change

The above listed products with firmware 6.10.0.1 will begin shipping from the factory by **February 27, 2015**.

If you have any questions, please contact your sales representative or Lantronix Customer Support at (866) 649-0721 or (949) 453-3990 x342.