

PCN No. 089

Date: March 27, 2008

## Product Change Notice: XPort Web Manager Version 1.6.0.2

Dear Valued Lantronix Customer,

Lantronix PCN No. 080 contained incorrect information regarding Web Manager version 1.6.0.2. **Please note: Web Manager 1.6.0.2 was not shipped on XPort products with the initial release of firmware version 6.5.0.7.**

At this time, Lantronix is pleased to announce the release of the updated and improved version 1.6.0.2 XPort Web Manager. Web Manager 1.6.0.2 will ship on the XPort products listed in the table below within the next 4 weeks.

For quality and tracking purposes, the manufacturing revision numbers on the product label will be changed. New revision numbers are also listed in the table.

### Release Highlights: New Features

- The ability to turn off the display of the remote IP address in modem mode
- The ability to use a broadcast address with UDP
- The ability to have the XPort Link Status reported on an I/O pin

### Upgrade/Update Process

No special upgrade/update procedure is necessary.


### XPort Part Numbers affected:

XPort Part Numbers	Description	Current Revision	New Revision
XP1001000-03R	Standard RoHS XPort, Extended Temperature	C12	D12
XP1001001-03R	Standard RoHS XPort, Commercial Temperature	C12	D12
XP1002000-03R	RoHS XPort, AES Encryption, Extended Temperature	C12	D12
XP1002001-03R	RoHS XPort, AES Encryption, Commercial Temperature	B12	C12
XP100200S-03R	RoHS XPort Encrypted Sample Tin	C12	D12
XP100200K-03	XPort Evaluation Kit	D15	E15
XP1004000-03R	RoHS XPort RS-485	D12	E12
XP1001000-03-GC-R	Grid Connect RoHS XPort, Extended Temperature	B12	C12
XP1001001-03R-AP	Asia Pacific RoHS XPort, Commercial Temperature	B12	C12
XP100400S-03R	RoHS XPort RS-485 Sample Tin	C12	D12

PCN No. 089

## Revision Tracking Information on XPort Label

Please note that the revision information for the XPort product is on the label in the location shown below:



## SUMMARY:

XPort factory shipments with Web Manager 1.6.0.2 will be phased in over the next 4 weeks. The Web Manager version can be verified by examining the label for the product revision number.

For more information, please contact your Lantronix Field Application Engineer or Lantronix Customer Support at (866) 649-0721 or (949) 453-3990 x 342.